

### Description:

6 Mil Polyethylene Vapor Barrier, seams taped Vinyl Dura-cushion Pads, stapled to bottom 2 Layers of 4 ply Douglas Fir, glued & stapled Moistop Vapor Barrier, under flooring 3/4" X 2 1/4" Solid Hard Rock Maple Flooring

### Features & Benefits:


- **Quality Materials, no need to replace in 10-20 years**
  - **Superior Craftsmanship, built sturdy, won't fall apart**
  - **All Inclusive Easy to Understand Pricing, simple, less hassles, no nickel and diming**
  - **Lifetime Limited Warranty, no out of pocket repair bills because of faulty materials or workmanship\***  
 (Backed with Over 60 Years Experience)
- \*does not cover moisture, maintenance or water related problems




### Specifications:

<b>SYSTEM TYPE</b>	Floating System	<b>SLAB DEPRESSION</b>	3/8" pad: 25/32" flooring – 2 1/8" 33/32" flooring – 2 3/8"	5/8" pad: 25/32" flooring – 2 3/8" 33/32" flooring – 2 5/8"
<b>FLOORING TYPE</b>	Hard Rock Maple or customer choice	<b>TESTING LABORATORY</b>	United States Sports Surfacing Laboratory	
<b>ANCHORAGE</b>	No concrete attachment	<b>CERTIFIED TESTING</b>	Laboratory test equipment	
<b>SUBFLOOR CONSTRUCTION</b>	Plywood Panel	<b>GREEN STATUS</b>	Managed forests, certification available calibrated and certified through the ISSS	
<b>RESILIENCE</b>	PVC Pads			


WALL BASE DETAIL



THRESHOLD DETAIL (optional accessory)



EQUIPMENT DETAIL (optional accessory)



**Tacinelli Sports Floor Systems**  
 P.O. Box 117, Billings, NY 12510  
 1-888-404-WOOD  
 cdtacinelli@tacinelli.com  
 www.bestportsfloors.com